



Effikal brand vent dampers are included as original equipment on many gas boilers used for home heating. Some Effikal brand vent dampers manufactured between July 1, 2007 and March 1, 2008 have developed cracks on the plastic ears connecting the motor assembly to the mounting bracket. If both ears break, the motor assembly could disconnect from the bracket.

For more information, [Click Here](#) for the U.S. Consumer Product Safety Commission (CPSC) News Release

Please answer the following questions in order. If you are unable to determine whether or not you are subject to the recall, please contact your HVAC service contractor immediately.

1) Do you have a **GAS** Boiler manufactured by one of the following companies?

Manufacturer	Atmospheric Gas Boiler Models	Vent Damper Date Codes	Vent Damper Serial Numbers
Allied Engineering	MG, MS and SG series	0728-0809	3588428-3687571
Burnham	Series 2b, Series 8h, and Independence except Independence PV	0728-0738	3588428-3647820
Crown	AWI, CWI and BSI series	0728-0809	3588428-3687571
Hydro Therm	R/MR, VGA, VS and HW series	0728-0809	3588428-3687571
Laars	JV series	0728-0809	3588428-3687571
Lochinvar	CBN Solution series	0728-0809	3588428-3687571
RBI	Spectrum series	0728-0809	3588428-3687571
Smith	GB and HW series	0728-0809	3588428-3687571
New Yorker	CG and CGS series	0728-0738	3588428-3647827
Peerless	MI, 63 and GM series	0728-0809	3588428-3687571
Raypak	Series XV-42-180, Series V-181-260 and 182-261, Series VII-133	0728-0809	3588428-3687571
Union Steam	GWA and GSA	0728-0809	3588428-3687571
Weil-McLain	CGa, EG, and PFG series	0728-0738	3538074-3647830
WilliamsonThermoflo	GWA and GSA	0728-0738	3538074-3647830

2) Does the boiler include a gas vent damper with a black plastic cap and base?
(It should be located on top of the boiler connected to the vent pipe.)



- 3) What is the serial number located on the black cap?
Please write Serial # here _____



- 4) Contact your HVAC service contractor.
- Provide the serial number information.
 - Provide the contractor with the webpage www.effikal.com/contractor
 - Provide the contractor with the following replacement information
 - 1) Part: #70009000
 - 2) Model: RMA-AL
 - 3) Description: Replacement Motor Assembly (Aluminum Base)
 - 4) Inform the HVAC service contractor to contact their wholesale distributor for the unit and the replacement program details.
- 5) Schedule a “NO CHARGE” replacement of the affected gas vent damper motor assembly with your HVAC service contractor.